

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MD,  
19-NEMA V,  
2-

S.F. Barber House  
New Market Vicinity  
St. Mary's County  
Maryland

HABS No. MD-872

Randolph Langenbach, Photographer 1973

- MD-872-1 SOUTH ELEVATION , NOTE DETERIORATION OF ROOF AND WALLS
- MD-872-2 EAST (GABLE) ELEVATION
- MD-872-3 EAST ELEVATION, DETAIL OF WALL WITH CHIMNEY OPENING
- MD-872-4 NORTH ELEVATION, VIEW SHOWING RIVEN CLAPBOARD UNDER PLATE
- MD-872-5 GROUND FLOOR, EAST ROOM, SOUTHWEST CORNER
- MD-872-6 GROUND FLOOR, EAST ROOM, EAST WALL (ALMOST COMPLETELY DESTROYED)